



GE MapSight™ Tech Tip

Care Tips for the Tripod

The tripod should always be utilized to ensure stability in capturing the target coordinates within the TrueSize image. Here are some tips to maximize the life of the tripod:


Unlocking the Tripod Legs

1) Only turn the leg locking mechanism a quarter turn when extending the legs. If you loosen this locking mechanism too much the leg can fall out.



Lever Position When Storing Tripod

2) Turn the grey locking lever, on the tripod head, to the locked position when it is being put away. This moves the locking lever in a position where it will be less likely to be damaged, particularly when storing.



Using the Cover

3) To protect the tripod use the tripod cover when putting the tripod away.

